



BOREHOLE & CPT LOG

HOLE NO.:

BH/CPT-1
& CPT-2

CLIENT: Client 1

PROJECT: Geotechnical Investigations

JOB NO.:

Demo 2a

SITE LOCATION: 33 Hedgehog Road, New Brighton

CO-ORDINATES: 1573911.2mE, 5181543.0mN (NZTM)

CONTRACTOR: Internal

RIG:


ELEVATION: 2.65m (NZVD2016)

DRILLER: John

START DATE:

END DATE: 21/05/2019

LOGGED BY: John



REMARKS

Soil Behaviour Type (SBT) - Robertson et al. 1986

- | | |
|---|---|
| 0 Undefined | 5 Sand mixtures: silty sand to sandy silt |
| 1 Sensitive fine-grained | 6 Sands: clean sands to silty sands |
| 2 Clay - organic soil | 7 Dense sand to gravelly sand |
| 3 Clays: clay to silty clay | 8 Stiff sand to clayey sand |
| 4 Silt mixtures: clayey silt & silty clay | 9 Stiff fine-grained |

PO Box 8952, Riccarton
CHRISTCHURCH

Ph:021 044 1852

Email: info@geroc.biz



BOREHOLE & CPT LOG

HOLE NO.:

BH/CPT-1
& CPT-2

CLIENT: Client 1

PROJECT: Geotechnical Investigations

JOB NO.:

Demo 2a

SITE LOCATION: 33 Hedgehog Road, New Brighton

CO-ORDINATES: 1573911.2mE, 5181543.0mN (NZTM)

CONTRACTOR: Internal

RIG:


ELEVATION: 2.65m (NZVD2016)

DRILLER: John

START DATE:

END DATE: 21/05/2019

LOGGED BY: John



REMARKS

Soil Behaviour Type (SBT) - Robertson et al. 1986

- | | |
|---|---|
| 0 Undefined | 5 Sand mixtures: silty sand to sandy silt |
| 1 Sensitive fine-grained | 6 Sands: clean sands to silty sands |
| 2 Clay - organic soil | 7 Dense sand to gravelly sand |
| 3 Clays: clay to silty clay | 8 Stiff sand to clayey sand |
| 4 Silt mixtures: clayey silt & silty clay | 9 Stiff fine-grained |

PO Box 8952, Riccarton
CHRISTCHURCH

Ph:021 044 1852

Email: info@geroc.biz