



HEALTH & SAFETY

JOB NO.: Demo 2a

CLIENT: Client 1
PROJECT: Geotechnical Investigations
LOCATION: 33 Hedgehog Road, New Brighton
REPORT COUNT: 1

Arrival on site 13/12/2018 at 2:30PM

Completed By: HS

General items to check

Have you reviewed the personal H&S checklist?	YES
Required Personal Protective Equipment (PPE):	Hard Hat
Other required PPE?	
Have you read the Site Hazard Board and acknowledged hazards and mitigations?	YES
Hazard Board comments:	
Was there a hazard that prevented you from going on site?	N/A
If yes, please describe hazard:	N/A
Has the hazard been notified to the Site Manager?	N/A
Has the hazard been notified to your Manager?	N/A
Additional comments:	
Photo of Site Hazard Board displayed:	

Hazards

Nature of hazard:	Wet site - Slip hazard
GPS location:	1,1
Remarks:	Wet floor signs placed appropriately
Photos:	